



SERVICE MANAGEMENT

NEWS LETTER



ATTN: SERVICE MANAGER

DATE 4-25FILE REF. 1NO. 63-14

SUBJECT: INDEX OF 1963 NEWS FLASH AND SERVICE MANAGEMENT LETTERS

We are pleased to provide a compiled index of all News Flash and Service Management letters released to date on 1963 products. Although this material is now being filed in accordance with subject matter in the Service Information Binder, we believe these indexes will serve as an additional valuable aid in finding corrections to problems and other information.

1963 - NEWS FLASHES

<u>No.</u>	<u>Subject</u>	<u>File Ref.</u>
63-1	1963 Model News Flash Numbering Sequence & File Reference	1
63-2	1963 Factory Fill Engine Oil Level	13
63-3	1963 -- Pontiac and Tempest Models	21
63-3A	Tempest Brake Line	9
63-4	1963 Body to Frame Mounting Locations	3
63-5	Tempest Automatic Transmission Downshift Wire	12
63-6	1963 V-326 Engine in Tempest with Automatic Trans ..	14
63-7	1963 Pontiac Tail Lamp Wiring Harness	2
63-8	1963 Two-Year Engine Coolant	16
63-9	1963 Tempest LeMans Tail Lamp Assembly	2
63-10	Tempest Hood Adjustment on 1963 Tempest	4
63-11	Non-Glare Inside Rear View Mirror - 1963 Pontiac ...	18
63-12	Transistor Ignition Caution - Burned Voltage Regulator Points -- Use of "Sun Scope" Tachometer on Transistor Ignition System	17
63-13	Counterphased Rear Unit Gears	12
63-14	Tilt Steering Wheel Direction Signal Cancelling	17
63-15	RHM Cast Iron Governors	12
63-16	Vibrations Originating from Wheel Assembly	7
63-17	Revised RHM Front Clutch Plates	12
63-18	Cylinder Head Identification	13
63-19	Dead Battery or Blower Motor Burn Up - A/C Pontiacs -- Nozzle Lock-Up on Early A/C Tempests	19
63-20	Engine Oil Pan Leaks	13
63-21	Overheated Engine - A/C Tempest 326 Engine	19
63-22	1963 Tempest and Pontiac Rochester 2Bbl. Carburetor Changes	14
63-23	Tempest Automatic Transmission to Axle Carrier Bolts	10
63-24	Inoperative Door Locking Mechanism	2
63-25	Possible Radiator Leak - V-326 with Air Conditioning	19
63-26	1962 Pontiac Differential Assemblies in 1963 Cars ..	10
63-27	Governor Replacement Procedures	12
63-28	Tempest Air Conditioning Evaporator Drain Stoppage .	19
63-29	1963 Tilting Steering Column - Poor Return	8

<u>No.</u>	<u>Subject</u>	<u>File Ref.</u>
63-30	1963 Remote Control Mirror Installation	18
63-31	Oil Capacity Requirements Roto and Super Hydra-Matic Transmission	12
63-32	Shaft Seal Leaks - 6 Cylinder Air Conditioning Compressor	19
63-33	Tempest Wheel Stop Sleeve 9770659	8
63-34	Seat Belt Installation	18
63-35	Wheel Stud-Aluminum Integral Drum 536657-8	9
63-36	Accelerator Pedals Binding or "Popping" Off Ball Studs 23-29 Series	14
63-37	Idle Speed and Mixture Adjustments - 1963 Tempest ..	14
63-38	1963 Pontiac Custom Sports Wheel Disc Part Numbers 9771228-9, Front and Rear	7
63-39	Transistor Ignition Pick-Up Coil and Ignition Coil Test Reading	17
63-40	Removal of Alternator Regulator Capacitor from All 1963 Radio-Equipped Pontiacs and Tempests	17
63-41	Grand Prix Console Shift Indicator Light Flicker -- Headlamp Flicker - Pontiac and Tempest	17
63-42	Convertible Top Zippers	2
63-43	1963 Pontiac Trim Ring Squeak Part Number 548981 for Aluminum Brake Drum with Integral Hub	7
63-44	Revision of Hydra-Matic Basic T.V. Adjustment-1963 .	12
63-45	1963 Pontiac Shift Control Lever Rattle	12
63-46	Grille Bar Whistle - 23, 26, 28 Models	4
63-47	Aluminum Upper Accumulator Ring -- All Roto Hydra-Matics 61-63	12
63-48	1963 TempestTorque Service Notes and Shop Manual Revisions	12
63-49	Tachometer Testing	18
63-50	1963 Tempest Front Suspension Strut Rod Bushing	5
63-51	Engine Ignition Timing	13
63-52	Revision to Accessory Package Installation Instructions	18
63-53	Breakerless Ignition Malfunction	17
63-54	Verba-Phonic Rear Speaker Interference Noises	18
63-55	Dust and Water Leaks in Trunk Compartment	2
63-56	Tempest Lower Control Arm Ball Stud	5
63-57	1963 Power Steering Pump Pulley Wobble	8
63-58	Engine Overheating & Coolant Loss - All Pontiac and Tempest Models	16
63-59	421 H.O. Idle Speed Settings	14
63-60	New Governor for 1963 PG and PAH Models RHM	12
63-61	1963 TempestTorque Shift Indicator Lamp Socket Failures	17
63-62	Air Conditioning Compressor Belt	19
63-63	Tempest Steering Column Adjustment	8
63-64	1963 TempestTorque Turbine Shaft and Clutch Hub	12
63-65	Windshield Wiper Overtravel	17
63-66	New Distributor - 1963 Pontiac and Tempest	17
63-67	1963 Tempest Camshaft Coding	13
63-68	Wrench-Wheel Nut Socket and Jack Handle 521332	7
63-69	Possible Electrical Malfunctions 1963 Pontiac	17
63-70	1963 Tempest Steering Recovery	8
63-71	Tempest Lower Ball Stud	5

<u>No.</u>	<u>Subject</u>	<u>File Ref.</u>
63-72	1963 Tempest Direction Signal Failure to Cancel	17
63-73	1963 Tempest Torque Service Parts	12
63-74	Elimination of RHM Pressure Relief System	12
63-75	Grille Bar Whistle - 23, 26, 28 Models	4
63-76	Alternator Belt Whip - 326 and 389 Engine Except A/C	13
63-77	Cold Starting	13
63-78	Inoperative Windshield Wipers and/or Back-Up Lamps 1963 Pontiac	18
63-79	Procedure for Correcting Low Oil Pressure	13
63-80	Air Conditioning (Circ-L-Aire and Tri-Comfort) 1963 Pontiac	19
63-81	Frozen Shift Control Cable - 1963 Tempest	12
63-82	Remote Control Mirror - Cable Freeze Up	18
63-83	H-M Fluid Change -- H-M Governors	12
63-84	Rocker Panel Moldings - 1963 Pontiac	2
63-85	Radio Station Fade or Mix - 1962 and 1963 Pontiac and Tempest	18
63-86	Pontiac 4-Speed Synchro-Mesh Trans H.D. Gear Pkgs...	11
63-87	Pedal Travel - 1963 Pontiac H.D. Clutch	11
63-88	1963 Tempest Rear Brake Drum Removal	9
63-89	Cruise Control Repair Procedures	18
63-90	1963 Tempest Windshield Wiper Gear Service	17
63-91	1963 Custom Spinner Type Wheel Cover	7
63-92	Inoperative Reverberation Amplifiers - 1963 Pontiac	18
63-93	1963 Tempest V-326 Synchro-Mesh Throttle Return Spring Change	14
63-94	Parking Brake Cable - 1963 Tempest	9
63-95	1963 Tempest Differential Ring Gear Bolt Torque Specifications	10
63-96	Pontiac Horn Ring Rattle or Buzz	8
63-97	1963 Custom Spinner Type Wheel Cover	7
63-98	Improved Heater Water Hose Routing - 1963 Pontiac with Air Conditioning	19
63-99	Composite U-Joints - 1963 Pontiac	10
63-100	Elimination of RHM Input Shaft Rear Oil Seal Ring ..	12
63-101	Remote Control Rear View Mirror Cable Breakage - 1963 Pontiac and Tempest	18
63-102	Carter Carburetor - Choke Piston Change- 1963 Pontiac -- Carter Carburetor - Poor Throttle Return Pontiac and Tempest	14

1963 - SERVICE MANAGEMENT LETTERS

<u>No.</u>	<u>Subject</u>	<u>File Ref.</u>
63-1	1963 Pontiac and Tempest New Car Pre-Delivery and 60 Day or 2000 Mile Inspection and Adjustment Check Sheets	21
63-2	Service Management News Letter	1
63-3	Tempest Parking Brake Warning Light	21
63-4	Stator Oil Seal Installer J-21025	21
63-5	Special Policy on 61-62 RHM Aluminum Governor Replacement	12
63-6	New and Revised 1963 Model Flat Rate Operations	1
63-7	New and Revised 1963 Model Flat Rate Operations	1
63-8	Dealer Procedure - 2,000 Mile Inspection and Adjustment on New Pontiacs and Tempests Purchased by General Motors Corporation, Allied Division, or Subsidiary Companies	1
63-9	New and Revised 1963 Model Flat Rate Operations	1
63-10	Additional Time Allowance on Aluminum Governor Replacement	12
63-11	(1) Items Requiring Zone Approval on Warranty Work (Form 727) (2) Pre-Delivery or 2,000 Mile Inspection Expense (3) Maintenance Items (owner Expense)	1
63-12	Improper Warranty Repairs	1
63-13	Index of News Flash and Service Management Letters .	13